

MASSIVE DIAMOND MINING DISPOSAL

CONDITION REPORT CERTIFICATE				
LOT NO:	11			
MAKE:	RONDEBULT FRONT END LOADER			
TRANSMISSION	MANUAL		AUTOMATIC	X
COLOUR:	YELLOW			
YEAR:	2020			
REGISTRATION NO:				
ENGINE NO:				
VIN / CHASSIS / SERIAL NO:	KLA100083			
BODY:	GOOD RUNNING CONDITION.			
TYRES / TRACKS:	LEFT FRONT	25%	RIGHT FRONT	25%
	LEFT REAR	25%	RIGHT REAR	25%
	LEFT REAR +1		RIGHT REAR +1	
	SPARE WHEEL			
KILOMETRES / HOURS:	8066.0 HOURS			
INTERIOR:	FAIR CONDITION			
WINDSCREEN:	GOOD			
ENGINE & GEARBOX:	GOOD RUNNING CONDITION			
HYDRAULICS / TURNTABLE:	N/A			
ATTACHMENT CONDITION:	GOOD CONDITION, HYDRAULIC CYLINERS LEAKING			
UNDERCARRIAGE:	GOOD CONDITION			
GENERAL NOTES:	GOOD CONDITION			
KEYS:	1			