

# MASSIVE DIAMOND MINING DISPOSAL

CONDITION REPORT CERTIFICATE				
LOT NO:	12			
MAKE:	RONDEBULT ZL60 FRONT END LOADER			
TRANSMISSION	MANUAL		AUTOMATIC	X
COLOUR:	YELLOW			
YEAR:	2020			
REGISTRATION NO:				
ENGINE NO:				
VIN / CHASSIS / SERIAL NO:	ZL60 LA807848			
BODY:	GOOD RUNNING CONDITION. COOLER IS LEAKING.			
TYRES / TRACKS:	LEFT FRONT	40%	RIGHT FRONT	40%
	LEFT REAR	40%	RIGHT REAR	40%
	LEFT REAR +1		RIGHT REAR +1	
	SPARE WHEEL			
KILOMETRES / HOURS:	11038.8 HOURS			
INTERIOR:	GOOD. SEAT IS TORN.			
WINDSCREEN:	GOOD			
ENGINE & GEARBOX:	GOOD RUNNING CONDITION. COOLER IS LEAKING.			
HYDRAULICS / TURNTABLE:	HYDRAULIC CYLINDERS AND TANK IS LEAKING. OIL LEAK AT THE ARTICULATION JOINT.			
ATTACHMENT CONDITION:	GOOD CONDITION			
UNDERCARRIAGE:	GOOD CONDITION			
GENERAL NOTES:	GOOD CONDITION			
KEYS:	1			