

MASSIVE DIAMOND MINING DISPOSAL

CONDITION REPORT CERTIFICATE				
LOT NO:	5			
MAKE:	KOMATSU D475A-5 TRACK DOZER			
TRANSMISSION	MANUAL		AUTOMATIC	X
COLOUR:	YELLOW			
YEAR:	2007			
REGISTRATION NO:				
ENGINE NO:				
VIN / CHASSIS / SERIAL NO:	20138			
BODY:	GOOD RUNNING CONDITION. FRONT LEFT LIGHT BROKEN. REFURBISHED. DOOR WINDOW CRACKED. BOTH DOORS ARE CRACKED. WIRES ARE LOOSE.			
TYRES / TRACKS:	LEFT FRONT	TRAC KS - 40%	RIGHT FRONT	TRACK S - 40%
	LEFT REAR		RIGHT REAR	
	LEFT REAR +1		RIGHT REAR +1	
	SPARE WHEEL			
KILOMETRES / HOURS:	27725 HOURS			
INTERIOR:	FAIR			
WINDSCREEN:	FAIR			
ENGINE & GEARBOX:	GOOD RUNNING CONDITION. FRONT LEFT LIGHT BROKEN. REFURBISHED. DOOR WINDOW CRACKED. BOTH DOORS ARE CRACKED. WIRES ARE LOOSE.			
HYDRAULICS / TURNTABLE:	HYDRAULIC TANK LEAKS OIL. HYDRAULIC OIL LEAKS UNDER THE MACHINE. HYDRAULIC FLUID LOW.			
ATTACHMENT CONDITION:	GOOD CONDITION			
UNDERCARRIAGE:	GOOD CONDITION			
GENERAL NOTES:	GOOD CONDITION			
KEYS:	1			