

MASSIVE DIAMOND MINING DISPOSAL

CONDITION REPORT CERTIFICATE				
LOT NO:	7			
MAKE:	LIEBHERR LRT1090 MOBILE CRANE			
TRANSMISSION	MANUAL		AUTOMATIC	X
COLOUR:	WHITE			
YEAR:	2018			
REGISTRATION NO:				
ENGINE NO:				
VIN / CHASSIS / SERIAL NO:	53753			
BODY:	GOOD RUNNING CONDITION. IN EXCELLENT CONDITION. THE CAB ROOF GLASS IS CRACKED.			
TYRES / TRACKS:	LEFT FRONT	96%	RIGHT FRONT	96%
	LEFT REAR	96%	RIGHT REAR	96%
	LEFT REAR +1		RIGHT REAR +1	
	SPARE WHEEL			
KILOMETRES / HOURS:	4185 HOURS			
INTERIOR:	GOOD			
WINDSCREEN:	GOOD			
ENGINE & GEARBOX:	GOOD RUNNING CONDITION. IN EXCELLENT CONDITION. THE CAB ROOF GLASS IS CRACKED.			
HYDRAULICS / TURNTABLE:	N/A			
ATTACHMENT CONDITION:	CRANE EXTENDING BOOM OPERATES VERY WELL.			
UNDERCARRIAGE:	GOOD CONDITION			
GENERAL NOTES:	GOOD CONDITION			
KEYS:	1			