

MASSIVE DIAMOND MINING DISPOSAL

CONDITION REPORT CERTIFICATE				
LOT NO:	8			
MAKE:	VOLVO L350H FRONT END LOADER			
TRANSMISSION	MANUAL		AUTOMATIC	X
COLOUR:	YELLOW			
YEAR:	2018			
REGISTRATION NO:				
ENGINE NO:				
VIN / CHASSIS / SERIAL NO:	V3007			
BODY:	GOOD RUNNING CONDITION. THE BUCKET IS DENTED AND WELDED. . THE SEAT COVER DAMAGED.			
TYRES / TRACKS:	LEFT FRONT	30%	RIGHT FRONT	30%
	LEFT REAR	30%	RIGHT REAR	30%
	LEFT REAR +1		RIGHT REAR +1	
	SPARE WHEEL			
KILOMETRES / HOURS:	12802 HOURS			
INTERIOR:	GOOD			
WINDSCREEN:	CRACKED			
ENGINE & GEARBOX:	GOOD RUNNING CONDITION. THE BUCKET IS DENTED AND WELDED. THE SEAT COVER DAMAGED.			
HYDRAULICS / TURNTABLE:	N/A			
ATTACHMENT CONDITION:	GOOD CONDITION			
UNDERCARRIAGE:	GOOD CONDITION			
GENERAL NOTES:	GOOD CONDITION			
KEYS:	1			