

MASSIVE DIAMOND MINING DISPOSAL

CONDITION REPORT CERTIFICATE				
LOT NO:	9			
MAKE:	VOLVO L220H FRONT END LOADER			
TRANSMISSION	MANUAL		AUTOMATIC	X
COLOUR:	YELLOW			
YEAR:	2018			
REGISTRATION NO:				
ENGINE NO:				
VIN / CHASSIS / SERIAL NO:	V12168			
BODY:	GOOD RUNNING CONDITION. THE BUCKET WITH STRAIGHT CUTTING EDGE IS IN GOOD CONDITION. THE BUCKET IS DENTED ON TOP. BOTH DOOR WINDOWS ARE CRACKED. ALL WHEEL ARCHES ARE DAMAGED. MADE IN SWEDEN. BOTH TAIL LIGHTS ARE CRACKED. BUCKET HAS BEEN WELDED.			
TYRES / TRACKS:	LEFT FRONT	30%	RIGHT FRONT	30%
	LEFT REAR	30%	RIGHT REAR	30%
	LEFT REAR +1		RIGHT REAR +1	
	SPARE WHEEL			
KILOMETRES / HOURS:	15135 HOURS			
INTERIOR:	GOOD			
WINDSCREEN:	CRACKED			
ENGINE & GEARBOX:	GOOD RUNNING CONDITION. THE BUCKET WITH STRAIGHT CUTTING EDGE IS IN GOOD CONDITION. THE BUCKET IS DENTED ON TOP. BOTH DOOR WINDOWS ARE CRACKED. ALL WHEEL ARCHES ARE DAMAGED. MADE IN SWEDEN. BOTH TAIL LIGHTS ARE CRACKED. BUCKET HAS BEEN WELDED.			
HYDRAULICS / TURNTABLE:	N/A			
ATTACHMENT CONDITION:	GOOD CONDITION			
UNDERCARRIAGE:	GOOD CONDITION			
GENERAL NOTES:	GOOD CONDITION			
KEYS:	1			